

The image shows the interior of a wooden boat cabin. On the left, there is a galley with a brass faucet. In the center, a wooden mast is visible. To the right, there is a pilot berth with a yellow cushion. The cabin is filled with wood paneling and various fixtures like lights and a sink. Text annotations are overlaid on the image, pointing to specific features.

HIT: Good ventilation through deck hatches and opening ports.

MISS: Original portlights tend to leak.

MISS: Joinery conceals mast and inhibits inspection.

HIT: Pilot (or "pile-it") berth adds extra bunk for kids, off-watch naps, or gear.

MISS: Original boats were short on handholds. The owner added this wood strip beneath the portlights.

HIT: Nav station and galley well suited for offshore duty.