

# PS REFIT BILL CATALINA 22 SWING-KEEL PIVOT ASSEMBLY

	Materials	Labor	Hours*	Total
Hanger bolt hardware	\$42	-	-	\$42
Tools (air saw, drill bits, grinding burrs)	\$79	-	-	\$79
Fiberglass repair*	\$80	\$350	10 (7)	\$430
Keel removal	\$25	\$0	10	\$25
<b>TOTAL</b>	<b>\$226</b>	<b>\$350</b>	<b>20</b>	<b>\$576</b>

\* Total man hours, paid labor in parenthesis; fiberglass repair includes reglassing cabin liner to hull.