





HIT: Nav station (above) has plenty flat working space for charts, and vertical mounting area for electronics.

MISS: Abundance of wood means more maintenance.

HIT: The U-shaped galley (left) puts everything the cook needs at his fingertips.

MISS: Varnished cabin sole is slippery when wet...